TOSHIBA 9h08h860

FIG. 1A



FIG. 1B



P16671

T0E050 9h08hB60

FIG.2



TOE050"9h08h860

FIG. 3A



FIG. 3B

			208		209		
(N-2)th track (Groove)	Address mark	Sector number			Track number	CRC error code	(N-1)th track (Land)
(N-1)th track (Land)	Address mark	Sector number	Track number	CRC error code			Nth track (Groove)
Nth track (Groove)	Address mark	Sector number			Track number	CRC error code	(N+1)th track (Land)
(N+1)th track (Land)	Address mark	Sector number	Track number	CRC error code			(N+2)th track (Groove)
(N+2)th track (Groove)	Address mark	Sector number			Track number	CRC error code	(N+3)th track (Land)
			207				206
			204				

FIG. 3C

			208		209		
(N-2)th track (Groove)	Address mark	Sector number	Track number	CRC error code			(N-2)th track (Groove)
(N-1)th track (Land)	Address mark	Sector number			Track number	CRC error code	(N-1)th track (Land)
Nth track (Groove)	Address mark	Sector number	Track number	CRC error code			Nth track (Groove)
(N+1)th track (Land)	Address mark	Sector number			Track number	CRC error code	(N+1)th track (Land)
(N+2)th track (Groove)	Address mark	Sector number	Track number	CRC error code			(N+2)th track (Groove)
			205				206
			204				

P16671

FIG. 4



Epson Stabbed


Address region reproduction data
301
302
303
304
305
306
307
Groove tracking
Land tracking
Address reproduction error
350

FIG. 5

TOE050 9h08h860

FIG. 6A



FIG. 6B



FIG. 6C